



EXHIBIT SHOWING:

A 0.229 OF ONE ACRE TRACT OF LAND, LOCATED IN THE JOHN SMALL SURVEY NO. 183, KENDALL COUNTY, TEXAS, SAID 0.229 OF ONE ACRE TRACT BEING THAT CERTAIN TRACT OF LAND CALLED 0.230 ACRES. RECORDED IN VOLUME 713, PAGE 575, OFFICIAL RECORDS, KENDALL COUNTY, TEXAS.



THO IT



<u>LEGEND</u>

•

G

Ø

OELx

RECORD CALL PER VOLUME 617, PAGE 920 () OFFICIAL RECORDS, KENDALL COUNTY, TEXAS

SET 1/2" IRON ROD WITH A RED "MATKIN-HOOVER 0

ENG. & SURVEY." PLASTIC CAP

FOUND 1/2" IRON ROD (UNLESS NOTED OTHERWISE)

FOUND PK NAIL IN ASPHALT

0 4" METAL BOLLARD POST

AC A/C PAD

<u>@</u> SANITARY SEWER CLEANOUT

69 DOWN SPOUT E

ELECTRIC BOX

GAS VALVE

UTILITY POLE

8 MONITORING WELL

T **TELEPHONE BOX**

₩ WATER METER

W WATER VALVE

ELECTRIC (OVERHEAD)

ENGINEERING

& SURVEYING

1) FIELD WORK PERFORMED ON: MARCH 04, 2016
2) BASIS OF BEARING: WAS ESTABLISHED USING THE TRIMBLE VRS NETWORK,

NAD83, TEXAS STATE PLANE COORDINATE SYSTEM, SOUTH CENTRAL ZONE, 4204, US SURVEY FOOT, GRID.

3) ADDRESS: 110 BANDERA ROAD

4) THIS SURVEY WAS DONE WITHOUT THE BENEFIT OF A CURRENT TITLE COMMITMENT. THEREFORE ALL SETBACKS, EASEMENTS, ENCUMBRANCES AND RESTRICTIONS MAY NOT BE SHOWN HEREON, THE SURVEYOR DID NOT COMPLETE AN ABSTRACT OF TITLE.

5) ONLY APPARENT UTILITIES WERE LOCATED. NO ATTEMPT HAS BEEN MADE AS PART OF THIS SURVEY TO SHOW THE EXISTENCE, SIZE, DEPTH, CONDITION, OR LOCATION OF ANY UNDERGROUND UTILITY, FOR INFORMATION REGARDING UNDERGROUND UTILITIES PLEASE CONTACT THE APPROPRIATE AGENCY.



I HEREBY CERTIFY THAT THIS SURVEY WAS MADE ON THE GROUND, AND THAT TO THE BEST OF MY KNOWLEDGE AND BELIEF, THIS PLAT CORRECTLY REPRESENTS THE FACTS FOUND AT THE TIME OF THIS SURVEY.

DATE, MAY 04, 2016 JEFF BOFRNER JEFF BOERNER
REGISTERED PROFESSIONAL LAND SURVEYOR
TEXAS REGISTER TION NO. 4939
JOB NO. 16-40250 229 AC TITLE SURVEY