

nnovative approaches Practical results Dutstanding service

9601 McAllister Fwy, Suite 1008 • San Antonio, Texas 78216 • 210-298-3800 • FAX 210-298-3801

www.freese.com

October 6, 2017

Sean Reich P.E., PMP City Engineer 402 E. Blanco Boerne, TX 78006

Subject: Recommendation of Construction Contract Award for Richter Ave. Water Main Repl. & Oak Park Dr. Sewer Main Replacement Project

Dear Mr. Reich:

Bids for the above referenced project were opened by the City of Boerne on September 28, 2017 at 10:00 am. The bid tabulation, compiled by Freese and Nichols, Inc. (FNI), indicated that three companies submitted bids for the project. The companies are listed below in order of lowest bid to highest bid:

- M5 Utilities, LLC
- Coppera, LLC
- Black Castle General Contractor, LLC

FNI reviewed the bid tabulation for inconsistencies, balance of unit prices and mathematical errors. The bids ranged from \$375,739 to \$496,882.90. The average Total Bid Amount was \$438,707.37 and the Engineer's Estimate for the project was \$380,300.

M5 Utilities, LLC. was the apparent low bidder with a Total Bid Amount of \$375,739. Coppera, LLC was the apparent second low bidder with a Total Bid Amount of \$443,500.20. There were mathematical errors found with the high bidder (Black Castle) where the sum of the extended amounts is \$849.10 less than the \$497,732.00 amount written in the Total Bid Amount on the Bid Form. The error on the Black Castle Bid Form did not change the outcome of the bids received. The M5 Utilities, LLC bid is approximately 18% less than the second lowest bid and it is approximately 1% less than the Engineer's Estimate.

Based upon FNI's review of the references submitted by M5 Utilities, LLC., and review of the bid tabulation, the Contractor appears to be capable of performing the work on this project. As a result, FNI recommends that the Award of Contract for the Richter Ave. Water Main Replacement and Oak Park Dr. Sewer Main Replacement be granted to M5 Utilities, LLC.

If you have any questions concerning this recommendation please call (210) 298-3829 at your convenience.

Sincerely,

Freese and Nichols, Inc.

David T. Bennett, P.E., Project Manager

cc: Ryan Bass, City of Boerne Attachments: Bid Tabulation; Contractor Reference

CLIENT:CITY OF BORENEPROJECT:RICHTER AVE WATER MAIN REPLACEMENT AND OAK PARK DRIVE SEWER MAIN REPLACEMENTENGINEER:FREESE AND NICHOLS, INC.

 PROJECT #
 BOR16639

 BID DATE:
 9/28/2017

				M5 COPPE		PPERA	PERA BLACK CASTLE		
n No.	Description	Unit	Estimated Quantity	Unit Price	Extended Amount	Unit Price	Extended Amount	Unit Price	Extended Amount
	WA	TER							
	1 MOBILIZATION/DEMOBILIZATION (MAX OF 5% OF BID ITEMS 3 - 20)	LS	1	\$5,000.00	\$5,000.00	\$7,000.00	\$7,000.00	\$24,637.00	\$24,6
	2 PREPARATION OF RIGHT-OF-WAY (MAX OF 3% OF BID ITEMS 3 - 20)	LS	1	\$3,000.00	\$3,000.00	\$4,200.00	\$4,200.00	\$4,133.00	\$4,1
	3 EROSION AND SEDIMENTATION CONTROLS (SWPPP)	LS	1	\$2,500.00	\$2,500.00	\$2,500.00	\$2,500.00	\$1,580.00	\$1,5
	4 TRAFFIC CONTROL (INCLUDING ALL BARRICADES, SIGNS, ETC.)	LS	1	\$10,000.00	\$10,000.00	\$5,900.00	\$5,900.00	\$24,378.00	\$24,3
	5 TRENCH EXCAVATION SAFETY PROTECTION	LF	1110	\$3.00	\$3,330.00	\$60.00	\$66,600.00	\$1.00	\$1,1
	6 8" PVC WATER MAIN, REMOVE AND REPLACE EXISTING MAIN, C900, DR-14	LF	1110	\$98.00	\$108,780.00	\$40.00	\$44,400.00	\$113.00	\$125,4
	7 8" GATE VALVE	EA	5	\$1,500.00	\$7,500.00	\$1,500.00	\$7,500.00	\$1,888.00	\$9,4
	8 REMOVE AND REPLACE EXISTING FIRE HYDRANT AND GATE VALVE ASSEMBLY	EA	1	\$6,500.00	\$6,500.00	\$4,200.00	\$4,200.00	\$4,879.00	\$4,8
	9 3/4" WATER SERVICE LINE, REMOVE AND REPLACE EXISTING SERVICE	LF	435	\$43.00	\$18,705.00	\$23.00	\$10,005.00	\$54.00	\$23,4
1	0 3/4" WATER SERVICE, REMOVE AND REPLACE EXISTING SERVICE BOX & RECONNECT METER	EA	17	\$1,100.00	\$18,700.00	\$440.00	\$7,480.00	\$749.00	\$12,7
1	1 DI WATER MAIN FITTINGS	TON	0.7	\$4,000.00	\$2,800.00	\$5,606.00	\$3,924.20	\$6,647.00	\$4,6
1	2 TIE-IN TO EXISTING WATER MAIN (STA 1+00)	EA	1	\$2,500.00	\$2,500.00	\$2,500.00	\$2,500.00	\$3,424.00	\$3,4
1	3 8" x 8" TAPPING SLEEVE AND VALVE (STA 12+10)	EA	1	\$1,100.00	\$1,100.00	\$4,200.00	\$4,200.00	\$6,444.00	\$6, 4
1	4 16" STEEL CASING PIPE	LF	20	\$175.00	\$3,500.00	\$110.00	\$2,200.00	\$135.00	\$2,
1	5 TRACER WIRE LOCATE BOX (WATER MAINS)	EA	1	\$575.00	\$575.00	\$750.00	\$750.00	\$1,726.00	\$1,
1	6 ASPHALT PAVEMENT REPAIR	SY	795	\$50.00	\$39,750.00	\$100.00	\$79,500.00	\$71.00	\$56,·
1	7 CONCRETE CURB AND GUTTER REPAIR	LF	12	\$17.00	\$204.00	\$85.00	\$1,020.00	\$71.00	\$
1	8 CONCRETE SIDEWALK AND DRIVEWAY REPAIR	SY	9	\$45.00	\$405.00	\$180.00	\$1,620.00	\$142.00	\$1,
1	9 GRAVEL DRIVEWAY REPAIR	SY	17	\$35.00	\$595.00	\$210.00	\$3,570.00	\$36.00	\$
2	0 SODDING	SY	85	\$10.00	\$850.00	\$10.00	\$850.00	\$13.00	\$1,1
2	1 REMOVE AND REPLACE EXISTING FENCE AND GATE	LF	24	\$50.00	\$1,200.00	\$150.00	\$3,600.00	\$57.00	\$1,3
	TOTAL BID AMOUNT WATER =				\$237,494.00		\$263,519.20		\$312,4
	SANITAR	Y SEW	/ER						
	1 MOBILIZATION/DEMOBILIZATION (MAX OF 5% OF BID ITEMS 3 - 15)	LS	1	5,000.00	\$5,000.00	5,500.00	\$5,500.00	11,128.00	\$11,
	2 PREPARATION OF RIGHT-OF-WAY (MAX OF 3% OF BID ITEMS 3 - 15)	LS	1	3,000.00	\$3,000.00		\$2,500.00	3,424.00	\$3,
	3 EROSION AND SEDIMENTATION CONTROLS (SWPPP)	LS	1	8,500.00	\$8,500.00		\$1,000.00	3,560.00	\$3,
	4 TRAFFIC CONTROL (INCLUDING ALL BARRICADES, SIGNS, ETC.)	LS	1	17,000.00	\$17,000.00		\$4,100.00	9,768.00	<u>\$9,</u>
	5 TRENCH EXCAVATION SAFETY PROTECTION	LF	450		\$1,350.00		\$40,500.00	3.00	<u> </u>
	6 35 (ALL DEPTHS)	LF	450		\$43,650.00		\$23,400.00	135.00	<u></u> \$60,
	7 D3034, SDR-35	LF	350		\$26,250.00		\$36,036.00	118.00	\$41,
	8 6" SANITARY SEWER CLEANOUT	EA	10		\$1,750.00		\$8,500.00	1,039.00	\$10,
	9 ENCASEMENT)	EA	1	2,400.00	\$2,400.00	2,500.00	\$2,500.00	2,029.00	\$2,
	0 SANITARY SEWER TELEVISING	LF	450		\$2,475.00	10.00	\$4,500.00	7.00	\$3,
	1 ASPHALT PAVEMENT AND DRIVEWAY REPAIR	SY	444		\$22,200.00		\$44,400.00	71.00	\$31,
	2 CONCRETE CURB AND GUTTER REPAIR	LF	45		\$1,800.00	85.00	\$3,825.00	71.00	\$3,
	3 CONCRETE SIDEWALK AND DRIVEWAY REPAIR	SY	13		\$1,120.00		\$2,520.00	142.00	<u>\$3,</u>
	4 SODDING	SY	70		\$1,750.00		\$700.00	13.00	<u>پا</u> ر پار \$۱
1	TOTAL BID AMOUNT SEWER =			20.00	\$138,245.00		\$179,981.00	10100	\$184,4



CONTRACTOR REFERENCE CHECK

Owner:	City of Boerne			Person Contacted:	Edgar Munoz P.E.			
Project Name:	roject Name: Richter Ave. Sewer Main Replaceme			Telephone No.:	830-249-0600			
Project No.:	BOR16639			Date Time:	10/4/17- 1000			
Contacted By:	David Marotta			Representing:	FNI			
Reference Project:	Segment A Pipeli	no						
Project Description:	10 miles of 16" p		no					
Project Complete:		On Schedule:	⊠ Yes □ No	Completion Date:	November 2017			
Project Manager:	Jim Crawford	on Schedule.			November 2017			
Superintendent(s):	Lucas Webb							
E =	Excellent	G = <i>Goo</i>	d F	= Fair	P = Poor			
Rate the Manager in	the following cate	gories:						
Qualifications by expe	erience or skills	G	Professio	nal conduct and inte	grity G			
Ability to manage sub	contractors	G	Ability to work with changes G					
Comments:								
Rate the Superintend	ent in the following	ng categories:						
Qualifications by experience or skills G Profession				onal conduct and integrityG				
Ability to manage sub	G	Ability to	work with changes	G				
Comments:								
Rate the Contractor's work habits and quality of the work performed:								
Rate overall quality of finished project Significant rework required								
				ontrol procedures ad	equate			
Comments: Project is currently under construction but Mr. Munoz stated the project was being constructed in a quality manner.								
quality	manner.							

Rate the Contractor's project resources in the following categories:							
Adequate and skilled foreman	G	Equipment quantity and condition	G				
Adequate and skilled labor force	G	Appropriate use of equipment	G				
Comments:							
Rate the Contractor's financial manageme	nt and strength	:					
Financial resources adequate for project	G	Liens by subcontractors or suppliers	G				
Personnel wage disputes		Complaints of late or non-payment					
Comments:							
Rate the Contractor's ability to complete a	ind follow-up oi	n warranty work:					
Punchlist completed in reasonable time		Project staffed for timely completion					
Response on warranty work acceptable		Did Owner perform any warranty work	? 🗆 Yes 🗆 No				
Comments: Project is still under construc	ction.						
Would you recommend award of another contract to this Contractor? 🛛 Yes 🗌 No							
Comments or recommendations you would make to another owner:							



CONTRACTOR REFERENCE CHECK

Owner:	City of Boerne			Person Contacted:	Stan Scott		
Project Name:	Richter Ave. Sewer Main Replacement			Telephone No.:	830-537-5755		
Project No.:	BOR16639			Date Time:	10/3/17- 1400		
Contacted By:	David Marotta			Representing:	FNI		
Reference Project:	Segment A Pipeli	ne					
Project Description:	10 miles of 16" w						
Project Complete:		On Schedule:	⊠ Yes □ No	Completion Date:	November 2017		
Project Manager:	Jim Crawford	on seneaule.		completion bate.	November 2017		
Superintendent(s):	Lucas Webb						
Supermendent(s).							
E =	Excellent	G = <i>Goo</i>	d I	= = Fair	P = Poor		
Rate the Manager in	the following cate	gories:					
Qualifications by expe	erience or skills	G	Professio	nal conduct and inte	grity <u>G</u>		
Ability to manage sub	contractors	G Ability to work with changes G					
Comments:							
Rate the Superintend							
Qualifications by expe		G Professional conduct an			grity <u>G</u>		
Ability to manage sub	contractors	G	Ability to	work with changes	G		
Comments:							
Rate the Contractor's work habits and quality of the work performed:							
Rate overall quality of finished project Significan			t rework required				
Defective work correc		Quality c	ontrol procedures ad	lequate			
Comments: Project is still under construction but Mr. Scott stated project was being built in a quality manner.							

Rate the Contractor's project resources in the following categories:							
Adequate and skilled foreman	G	Equipment quantity and condition	G				
Adequate and skilled labor force	G	Appropriate use of equipment	G				
Comments:							
Rate the Contractor's financial manageme	nt and strength	:					
Financial resources adequate for project	G	Liens by subcontractors or suppliers	G				
Personnel wage disputes		Complaints of late or non-payment					
Comments:							
Rate the Contractor's ability to complete a	and follow-up or	n warranty work:					
Punchlist completed in reasonable time		Project staffed for timely completion					
Response on warranty work acceptable		Did Owner perform any warranty work	? 🗆 Yes 🗆 No				
Comments: Project is still under construc	ction.						
Would you recommend award of another contract to this Contractor? 🛛 Yes 🗌 No							
Comments or recommendations you would make to another owner:							